Pennsylvania Company for Insurances on Lives and Granting Annuities 304 Walnut Street Philadelphia Philadelphia County Pennsylvania

HABS No. PA-1463

TA TA 51-PHILA 586-

PHOTOGRAPHS

HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
Department of the Interior
Washington, D.C. 20240

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

1-1-

1

 $\Gamma = \{\{i_0, j_1\}, j_2\}$

ARCHITECTURAL DATA FORM

STATE	COUNTY		TOWN OR VICINITY		
PENNSYLVANIA	PHILADELPHIA		PHILADELPHIA		
HISTORIC NAME OF STRUCTURE (//	NCLUDE SOURCE FOR	R NAME)	all the life Warran assess.	HABS NO.	
PENNSYLVANIA COMPANY FOR IN	ISURANCES ON LIVE	ES AND			
GRANTING ANNUITIES	S ATDUCTURE			PA-1453	
SECONDARY OR COMMON NAMES OF STRUCTURE					
]	
COMPLETE ADDRESS (DESCRIBE LO	CATION FOR RURAL	L SITES)	<u> </u>		
304 Walnut Street		7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7			
DATE OF CONSTRUCTION (INCLUDE	E SOURCE)	ARCHITECT(S) //NC	(LUDE SOURCE)		
1859					
SIGNIFICANCE (ARCHITECTURAL A	ND HISTORICAL, INC	CLUDE ORIGINAL USE	OF STRUCTURE)		
Chartered in 1812, the company is the oldest institution of its kind in the nation.					
STYLE (IF APPROPRIATE)				,	
Italianate					
MATERIAL OF CONSTRUCTION (INC		- · - · - ·	1		
Brick with Pictou stone front. Rear buildings: common bond brick.					
SHAPE AND DIMENSIONS OF STRUC	TURE (SKETCHED FI	LOOR PLANS ON SEPA	RATE PAGES ARE	ACCEPTABLE)	
Measures approx. 25' (three-bay front) X 97'; two stories.					
EXTERIOR FEATURES OF NOTE The front facade has a smoo	th first floor a	and a rusticated	second floor.	The former is accen-	
tuated with spandrels and p	ilasters resting	g on plinths. Rou	und-arch window:	s on this facade	
are recessed and are nicely finished with stone frames and keystones. The street number,					
"304", is over the keystones of two first floor windows. (continued on page 2) INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)					
The original large banking	room was two sto	ories high and oc	ccupied front so	ection of the	
building, and had a second	floor gallery, w	which is still in	ntact. The original	inal offices were	
in the rear wing. Original dentiled cornice and skylig	interior element	cs include the fo	llowing: coved	ceiling with heavy narble (con't. on p. 2	
dentiled cornice and skylig MAJOR ALTERATIONS AND ADDITIONS	At in the center	basedoards, 51	mple Italian m	arole (con c. on p. 2	
WAJON ACTENATIONS AND ADDITIONS WITH DATES					
1			_		
PRESENT CONDITION AND USE					
APPROPRI				<u> </u>	
OTHER INFORMATION AS APPROPRIATE					
Old brick outhouse in the rear yard demolished 1961.					
COLUMN TO THE OR A TION (INC.)	TOTAL LISTING ON N	ATIONAL DEGISTER	CTATE PERISTERS	CTAI	
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) [Webster, Richard. Philadelphia Preserved. Philadelphia: Temple University Press, 1976.					
1859 insurance survey for 304 Walnut Street, name of insurance company not known.					
1005 11150101100 50110, 111	Of names office	, Humo or	1100 Company		
COMPILER, AFFILIATION		<u> </u>	DAT	TE	
	James C. Massey, HABS architect, November, 1961; Susan McCown, editor,				
Historic American Buildings	Survey, May 15	, 1984	111, 00000		

PENNSYLVANIA COMPANY FOR INSURANCES ON LIVES AND GRANTING ANNUITIES HABS No. PA-1453 (page 2)

> 4ABS PA, 51-PHILA,

> > 587-

EXTERIOR FEATURES OF NOTE (continued from page 1):

Also on this facade are segmental basement windows which are also decorated with keystones. The sash of all main windows consists of five upper lights and three lower lights. The entrance doorway is recessed like the windows, and is entered by a 4-step stoop. Double front doors each have one recessed panel, framed by a heavy bolection molding and decorated with lattice work. An oral peephole is cut in the center of each door. A semi-circular, 3-light transom with a keystone is over this doorway. A double cornice is at the roofline of the front facade. A single cornice is between first and second floor levels. Original shutters in the rear building are still intact (as of 1961).

INTERIOR FEATURES OF NOTE (continued from page 1):

fireplaces; yellow pine floor (since replaced); front door hardware (see HABS photo); 2-run open string stair with mahogany rail and octagonal newell; interior shutters (since removed).